

Jesse Escamilla III, P.E., S.E.

September 11th, 2017

Overview







Overview - Foundations/Bases/Hatch







Overview - "Telescoped" Seams




Overview - Chandelier




125 Towers Total – Anchorage Area




125 Towers Total – Glenn Highway



125 Towers Total – Wasilla




125 Towers Total – North Pole













Minnesota & Diamond Interchange




Inspection Plan

- Visual Inspection of Base
- Hand Torqueing Nuts
- Visual Inspection of Poles



Inspection Plan



Drone Inspection History

- 2014 Test drone images bridge inspection
- 2016 Trial drone contract for mast towers
 - Six towers tested
 - Varied wide angle and normal lenses
 - Varied Video and still images
- 2017 Contract of 31 towers for drone

New Inspection Plan

- Vicentariabites precontico Projeti Place Eield Inspection
- PlændeTorqueingPhatographs in Office
- Visual Inspection of Beles
- Hand Torqueing Nuts
- Visual Inspection of Poles*

*At predetermined locations


Drone Inspection Plan

- Photograph 1st quadrant with hatch
- Proceed up tower w/overlapping photos
- Detail specific irregularities
- Proceed clockwise to next quadrant
- Repeat until all quadrants are completed

Drone Inspection Example



Drone Inspection Example



Conclusions

- Better visual than previous inspections
- Ability to predetermine in-depth areas
- Ability to document inspections
- Ability to repeat inspection
- Full inventory within 4 years

Questions?

